1/4

Figure 1




Figure 2





Figure 3



 $X = 6 \text{ mm for DN} \le 50 \text{ mm}$

X = 4 mm for DN >= 60 mm

Figure 4

